



TruTool TKA 500 (2A1)

| 订货号 | | 备件 | | | |
|--------------|---------|-------------------|----|---------|------------------|
| No. D'ORDINE | | PEZZO DI RICAMBIO | 24 | 1208956 | |
| NO. DE REF. | | PIEZA DE RECAMBIO | 31 | 0359398 | USA 120V 50/60Hz |
| NO. DE REF. | | PIECE DE RECHANGE | 32 | 1261375 | USA 120V 50/60Hz |
| ORDER NO. | | SPARE PART | 33 | 1465246 | |
| NO BEST.-NR. | | ERSATZTEIL | 34 | 1926249 | |
| | | | 35 | 1933369 | |
| | | | 36 | 1893619 | |
| 1 | 1692842 | | 37 | 1893354 | D 230V 50/60Hz |
| 2 | 0207428 | | | 1893355 | CH 230V 50/60Hz |
| 3 | 1209000 | | | 1893356 | GB 110V 50Hz |
| 4 | 1209003 | | | 1893357 | USA 120V 50/60Hz |
| 5 | 0017159 | | | 1893354 | KR 220V 60Hz |
| 6 | 0353387 | | | 2007323 | CN 220V 50Hz |
| 7 | 0354170 | | 38 | 1893481 | D 230V 50/60Hz |
| 8 | 1214439 | | | 1893482 | CH 230V 50/60Hz |
| 9 | 0022330 | | | 1893483 | GB 110V 50Hz |
| 10 | 1227954 | | | 1893484 | USA 120V 50/60Hz |
| 11 | 1646214 | | | 1893481 | KR 220V 60Hz |
| 12 | 1208984 | | | 2007321 | CN 220V 50Hz |
| 13 | 1208985 | | 39 | 1951626 | |
| 14 | 1282892 | | 40 | 1938954 | |
| 15 | 1208987 | | 41 | 1911322 | |
| 16 | 0353514 | | 42 | 1938945 | |
| 17 | 1208988 | | 43 | 1907887 | |
| 18 | 0353932 | | 44 | 0760467 | |
| 19 | 0028185 | | 45 | 1880101 | |
| 20 | 0353533 | | 46 | 0353954 | |
| 21 | 0353384 | | 47 | 1208958 | |
| 22 | 1214438 | | 48 | 0136774 | |
| 23 | 1238823 | | 49 | 1880102 | |

